

Style Survey Coleford South 2026 Spring

Again the tree's in the area need looking at this seems to be the main problem in South Coleford where wood patch cover footpaths.

FR 4/4 all Fine.

FR 4/5 Style #45962 Fine

FR 4/6 KG ID37672 fine,

FR 4/8 fine.

FR 4/9 Bridge and K/G all good

Bridge ID 4465 well maintained

FR 4/15 KG ID 37471 Fine, Bridge ID4417 Fine, ID 37472 say style but it a KG Fine. KG ID 37620 not straight however works.



FR 4/17 KG fine Bridge in need of some attention. The KG in this area are being walked around and not used.



FR 4/18 KG not being used just being walked round

FR 4/19 KG by white gate Fine.

FR4/20 Style ID 37255 is I need of some work. New Step and more secure.

FR4/21 style has had another piece of wood across top, some may struggle as its quite high.



Same path further up hill a tree has fallen and needs moving. Style has completely broken.



FR4/22 Fine

FR 4/23 KG 2 both fine

FR 4/24 metal KG fine

FR 4/25 Steps go up the footpath clear at moment and the path clear, I believe that in the summer months this will become over grown again, I will keep an eye on it.

Going the opposite way over the little stream, are 2 very slimy pieces of wood to walk over, could really do with some chicken wire, so not slippery. It's hard to get over the stile as tree very over grown and hanging over stile.



FR 4/26 All fine

FR 4/27 All fine

FR 4/28 All fine

FR 4/29 All fine

FR 4/31 all fine



FR 4/33 As you go over the style from the field into the wooded area theres a fallen tree over the path. Style step broken. No stump available on one side. partial stump other side.

FR 4/62 the bridge has still not been fixed, however it is now much safer with harris fencing securely in place.

FR 4/64 All Fine

FR 4/66 All fine